

	RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC	
---	--	--

LIFTING GEARS INSPECTION checklist		Abu Dhabi/ Dubai
Date: 21-06-2023	Location: loc	Client abu dhabi
Project Code: ABU DHABI-COM-RESOURC		Project Details: ABU DHABI-COM-RESOURCES
Sl. No Of Lifting 1000	Detail Of Lifting details	

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
Equipment					
2	Lifting Gear Current Colour code?	✓			color code is applicable
3	Is the SWL displayed?	✓			swl
4	Does all the lifting gears stored properly?	✓			LG stored
5	In case of nylon/web slings, does protection from sharp edges exist?	✓			sharp edge
6	Are hook & safety latch & wire rope in good condition?	✓			latch and wire
7	Are all lifting tackles in good condition?	✓			good condition
Personnel					
8	Is the In-charge of lifting gears aware about the storing of lifting gears?	✓			aware
9	Does the In-charge aware of the inspecting of lifting gears for any physical defects?			✓	physical defects
10	Are all personnel involved in lifting appropriately trained?	✓			trained

Comments : my comments abt lg There are many variations of passages of Lorem Ipsum available, but the majority have suffered alteration in some form, by injected humour, or randomised words which don't look even slightly believable. If you are going to use a passage of Lorem Ipsum, you need to be sure there isn't anything embarrassing hidden in the middle of text. All the Lorem Ipsum generators on the Internet tend to repeat predefined chunks as necessary, making this the first true generator on the Internet.
--

Inspected By: K. Ramesh P. and R. R. R.	Site In charge: Rashed Khan
Sign/Date:	Sign/Date:
RAY No: 23-06-00015	RAY No: 23-06-00015