



RAY International Electrical Contracting & Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

MOBILE CRANE CHECKLIST

Abu Dhabi/ Dubai

Date: 15-05-2025

Location: kannur1

Client: client-247

Project Code: Project-247

Project Details: Project-247

Site In charge: Employee-16

Registration No.: g

Make & Model: nn

Driving license 16-05-2025
Expiry:

Operator Name: e

Other Info: Test Info

Sl. No	ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN
		YES	NO	NA		
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)		✓			
2	Is crane third party certificate available?		✓			
3	Is operator third party certificate available?		✓			
4	Engine oil level		✓			
5	Engine coolant level		✓			
6	Hydraulic system oil level		✓			
7	Seat Belts		✓			
8	Condition of Battery and Lamps		✓			
9	Condition of wind screen & windows		✓			
10	Revolving lights in working condition.		✓			
11	Guards of moving and rotating parts		✓			
Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No: 1

Sl. No	ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN
		YES	NO	NA		
12	Horn		✓			
13	Reverse Alarm		✓			
14	Air conditioner		✓			
15	Tyre pressure & Tyre condition		✓			
16	Hook and Hook Latch		✓			
17	Over-Hoist, Boom Limit Switches working		✓			
18	Over load trip.		✓			
19	Boom Angle indicator		✓			
20	Safe Working Load indicator		✓			
21	Boom Brake & Lock		✓			
22	Main clutch		✓			
23	Deterioration or leakage in lines, tanks, hoses, valves, pumps, cylinders and other parts of air or hydraulic system		✓			
24	Fire Extinguisher in operator cabin		✓			
25	Third party certificates of operator and equipment		✓			
26	Load chart provided		✓			
27	Operator manual in crane		✓			
28	Lattice boom lowered to ground and fully inspected		✓			
Ref No: FR-604		Version. No	01	Issued Date	08.09.2016	Page No: 2

Sl. No	ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN
		YES	NO	NA		
29	Condition of the slings		✓			
30	Soil Condition		✓			
31	Safe distance from edge of excavation		✓			
32	Out riggers fully extended		✓			
33	Outrigger pads in good condition		✓			
34	Stability of crane		✓			
35	Wheel chokes available		✓			
36	Anemometer in working condition.		✓			
37	Overhead And Below Ground, Minimum Limit Approach Regulation At All Times		✓			
38	Safe Distance From Respective Equipment And Lines		✓			

General Comments : qwe

Inspected By : VINI11	Site I/C : Employee-16
Sign/Date : 	
RAY No : Emp-16	RAY No : Emp-16

Signature: