

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

MOBILE CRANE CHECKLIST							Abu Dhabi/ Dubai		
Date: 29-10-20	29-10-2024 Location : abc				Client:				
Project Code: ABU DHABI-COM-RESOURCES			Projec	Project Details: ABU DHABI-COM-RESOURCES					
Site In charge: Sudheer Thirumalmel Kalarickal				Registration No.: d					
Make & Model:	d				Driving license Expiry:	е	30-10-2024		
Operator Name:	d				Other Info:	Te	est Info		

OL N		COMPLIANCE			REMARKS	ACTION TO BE TAKEN		
SI. No	ITEMS	YES	NO	NA				
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)	~						
2	Is crane third party certificate available?		✓					
3	Is operator third party certificate available?		✓					
4	Engine oil level		✓					
5	Engine coolant level	√						
6	Hydraulic system oil level		✓					
7	Seat Belts		√					
8	Condition of Battery and Lamps		√					
9	Condition of wind screen & windows	✓						
10	Revolving lights in working condition.		✓					
11	Guards of moving and rotating parts		√					

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	1
---------	--------	-------------	----	-------------	------------	----------	---

		COMPLIANCE			RF	MARKS	ACTION TO BE TAKEN		
SI. No	ITEMS	YES	NO	NA			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	3E 17111E11	
	Horn		✓						
12			`						
	Reverse Alarm		√						
13			'						
	Air conditioner		√						
14			`						
''									
	Tyre pressure & Tyre condition		,						
15			✓						
13									
	Hook and Hook Latch	 							
40	111211	✓							
16									
	Over-Hoist, Boom Limit								
4-	Switches working		✓						
17									
	Over load trip.								
	Over load trip.		✓						
18									
	Doors Angle indicates								
	Boom Angle indicator		✓						
19									
	Safe Working Load indicator		✓						
20									
	Boom Brake & Lock		✓						
21									
	Main clutch		✓						
22									
	Deterioration or leakage in		✓						
23	lines, tanks, hoses, valves, pumps, cylinders and other								
	parts of air or hydraulic system								
	Fire Extinguisher in operator	√				•			
24	cabin	*							
	Third party certificates of								
25	operator and equipment		✓						
23									
	Load chart provided								
00	2000 011011 p.011000		✓						
26									
	Operator manual in crane	1	-						
	- Sporator manadi in ordino		✓						
27									
	Lattice boom lowered to	1	 						
	ground and fully inspected		✓						
28									
Ref No:	FR-604 Version. No	1 ()1	Issued	Date	08.09.2016	Page No:	2	
	10.000.110								

SI. No	177140	COMPLIANCE			RE	MARKS	ACTION TO BE TAKEN
51. NO	ITEMS	YES	NO	NA			
	Condition of the slings		✓				
29							
	Soil Condition		✓			·	
30			·				
	Safe distance from edge of		√			·	
31	excavation		·				
	Out riggers fully extended	√					
32		·					
	Outrigger pads in good		√				
33	condition		·				
	Stability of crane		√			•	
34			·				
	Wheel chokes available	√			·		
35		,					
	Anemometer in working		√				
36	condition.		·				
00							
	Overhead And Below Ground,		√		·		
37	Minimum Limit Approach		·				
•	Regulation At All Times						
	Safe Distance From		√				
38	Respective Equipment And		·				
00	Lines						
Conoral Car	d amenta i				1		
General Con	iments:						
Inspected B	y: abc			Site	e I/C :	Sudheer Thirun	nalmel Kalarickal
Sign/Date :				•			
Jigin Date .							
RAY No :	RU/022			RA	Y No :	RU/022	

Signature:

Ref No: FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	3	
----------------	-------------	----	-------------	------------	----------	---	--