RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

PPE INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 08-04-2025	**Location:** knr	**Client:** client-277
Project Code: Project-277	**Project Details:** Project-277	
Site In charge: Employee-16		

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
1	Are all personnel provided with the right & required personal protective equipment's (PPEs)?	✓			
2	Are the PPEs suitable for guarding against exposure to hazards involved?	✓			
3	Are signs, designating the areas where specific PPEs are to be used, posted?	✓			
4	Are the PPEs in good condition for providing safe shield?	✓			
5	Are adequate stocks of spare PPEs available at stores?	✓			
6	Do personnel know when & how to obtain replacement of PPEs?	✓			
7	Do personnel have difficulty in obtaining replacement of PPEs?	✓			
8	Are personnel equipped with clear lenses eye protection for work during dark hours?	✓			
9	Does the PPE stored in a clean and hygienic condition?	✓			
10	Are all visitors using mandatory PPE at the site?	✓			
11	Does the PPE used at the site meet the approved standard?	✓			
12	Does all the helmets fitted with cradle and in good condition?	✓			
13	Are all workers wearing suitable hand gloves for the job?	✓			
14	Are all workers wearing RAY coverall and as appropriate for sub-contractors?	✓			
15	Are all the persons wear safety shoes suitable for the job and in good condition?	✓			
16	Are all workers wearing suitable ear protection according to the noise level in the area?	✓			
17	Are all person working for (Welding, Grinding, cutting, bending etc.,) using face protection suitable for the job?	✓			
18	Are all required PPE available in the Guard Room for visitors?	✓			

General Comments ewq

Inspected By :	VINI11	**Site I/C :**	Employee-16
Sign/Date :			
RAY No :	Emp-40	**RAY No :**	Emp-16

Signature: