



RAY International Electrical Contracting & Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

PPE INSPECTION CHECKLIST

Abu Dhabi/ Dubai

Date: 19-06-2023

Location: g

Client: fvvv

Project Code: 005

Project Details: ,mjutgh

Site In charge: Vanthya Devan Sellaperumal

Sl. No	ITEMS	COMPLIANCE			REMARKS
		YES	NO	NA	
1	Are all personnel provided with the right & required personal protective equipment's (PPEs)?		✓		
2	Are the PPEs suitable for guarding against exposure to hazards involved?		✓		
3	Are signs, designating the areas where specific PPEs are to be used, posted?		✓		
4	Are the PPEs in good condition for providing safe shield?		✓		
5	Are adequate stocks of spare PPEs available at stores?		✓		
6	Do personnel know when & how to obtain replacement of PPEs?		✓		
7	Do personnel have difficulty in obtaining replacement of PPEs?	✓			
8	Are personnel equipped with clear lenses eye protection for work during dark hours?	✓			
9	Does the PPE stored in a clean and hygienic condition?	✓			
10	Are all visitors using mandatory PPE at the site?	✓			
11	Does the PPE used at the site meet the approved standard?		✓		
12	Does all the helmets fitted with cradle and in good condition?		✓		
13	Are all workers wearing suitable hand gloves for the job?	✓			
14	Are all workers wearing RAY coverall and as appropriate for sub-contractors?		✓		
15	Are all the persons wear safety shoes suitable for the job and in good condition?		✓		
16	Are all workers wearing suitable ear protection according to the noise level in the area?	✓			
17	Are all person working for (Welding, Grinding, cutting, bending etc.,) using face protection suitable for the job?		✓		
18	Are all required PPE available in the Guard Room for visitors?		✓		

General Comments bf

Inspected By : treesaSang

Site I/C : Vanthya Devan Sellaperumal

Sign/Date :

Sign/Date :

RAY No : 23-06-00002

RAY No : 23-06-00002

Ref No: 01

Version.

01

Issued Date

6/26/2023

Page No:

1