



RAY International Electrical Contracting and Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

STOP/ NEAR MISS REPORT

Abudhabi/ Dubai

Document No: 23-05-00097

Project: RU/021/22/PRJ

Activity: Replacement of porcelain insulator to polymer in 11 kV

Type: NearMiss

Classification:

Observation: The lineman stands on the truck while positioning of the bucket truck for j

Corrective Action: The driver and workers were strictly instructed not to stand in the vehicle

Photo:

Observed by: Ervin Sumangid